




# Preventive Maintenance Inspection

*Date:*

*2/20/02*

2500 kilowatt SHIP SERVICE DIESEL GENERATOR  
INSPECTION  
M/S MAHIMAHI  
MATSON NAVIGATION

File name	Time	Date
<b>C07.tif</b>	10:02:31 AM	12/13/99



IR Text Comment	Value
Section	Room
Equipment	
Additional information	
Fault	
Recommendation	No action

Object parameter	Value	
Emissivity	0.96	-
Object distance	0.0 m	-
Ambient temperature	23.0°C	-
Reference temperature	*	-
Label	Value	Diff temperature
IR : max	83.4°C	-
IR : min	38.4°C	-
SP01	73.2°C	*


### Description

Place for individual description.

File name	Time	Date
-----------	------	------

**C06.tif**

10:02:14 AM 12/13/99




IR Text Comment	Value
Section	Room
Equipment	
Additional information	
Fault	
Recommendation	No action

Object parameter	Value	
Emissivity	0.96	-
Object distance	0.0 m	-
Ambient temperature	23.0°C	-
Reference temperature	*	-
Label	Value	Diff temperature
IR : max	59.3°C	-
IR : min	40.7°C	-
SP01	51.9°C	*

### Description

Place for individual description.

File name	Time	Date
<b>C07.tif</b>	10:02:31 AM	12/13/99




IR Text Comment	Value
Section	Room
Equipment	
Additional information	
Fault	
Recommendation	No action

Object parameter	Value	
Emissivity	0.96	-
Object distance	0.0 m	-
Ambient temperature	23.0°C	-
Reference temperature	*	-
Label	Value	Diff temperature
IR : max	83.4°C	-
IR : min	38.4°C	-
SP01	73.2°C	*

### Description

Place for individual description.

File name	Time	Date
<b>D13.tif</b>	05:07:28 PM	12/13/99




IR Text Comment	Value
Section	Room
Equipment	
Additional information	
Fault	
Recommendation	No action

Object parameter	Value	
Emissivity	0.92	-
Object distance	0.0 m	-
Ambient temperature	23.0°C	-
Reference temperature	*	-
Label	Value	Diff temperature
IR : max	36.9°C	-
IR : min	29.4°C	-
SP01	30.2°C	*

**Description**

**RESCANNED OKAY**

File name	Time	Date
<b>D14.tif</b>	05:08:52 PM	12/13/99



IR Text Comment	Value
Section	Room
Equipment	
Additional information	
Fault	
Recommendation	No action

Object parameter	Value	
Emissivity	0.92	-
Object distance	0.0 m	-
Ambient temperature	23.0°C	-
Reference temperature	*	-
Label	Value	Diff temperature
IR : max	38.9°C	-
IR : min	29.3°C	-
SP01	30.6°C	*

### Description

Place for individual description.



## Summary of inspection

Place for general comments.

This quick report uses the Text Comment function in the ThermoCAM and the ThermoCAM Reporter PC software.

Section	Equipment	Fault	Recommendation
Room			No action
Room			No action
Room			No action
Room			No action
Room			No action